



Micron 1100 Firmware Update M0MU033 and M0MA033

PCN: 33180

Published: 2019-04-10

Type: Firmware Revision

Description: Changes and improvements made in firmware M0MU033 and M0MA033 over previous firmware M0MU031 and M0MA031 are:

- Enhancement to close a security vulnerability
- Unexpected Power Loss Improvements

Updating directly from all older revisions is supported. However, please note that reverting to any prior firmware revision is prevented after updating.

Reason: Improved Product Quality and Reliability

Product Affected: Micron 1100 SSD Product family

Affected Micron Part Number Component	Recommended Replacement	Customer Part Number
MTFDDAK1T0TBN-1AR12ABYY		?
MTFDDAK1T0TBN-1AR1ZABYY		?
MTFDDAK256TBN-1AR12ABYY		?
MTFDDAK256TBN-1AR12TAYY		
MTFDDAK256TBN-1AR1ZABYY		?
MTFDDAK2T0TBN-1AR12ABYY		?
MTFDDAK2T0TBN-1AR1ZABYY		?
MTFDDAK512TBN-1AR12ABYY		?
MTFDDAK512TBN-1AR1ZABYY		?
MTFDDAV1T0TBN-1AR12ABYY		?
MTFDDAV1T0TBN-1AR1ZABYY		?
MTFDDAV1T0TBN-1AR1ZTAYY		
MTFDDAV256TBN-1AR12ABYY		?
MTFDDAV256TBN-1AR12TAYY		?
MTFDDAV256TBN-1AR1ZABYY		?
MTFDDAV256TBN-1AR1ZTAYY		
MTFDDAV512TBN-1AR12ABYY		?
MTFDDAV512TBN-1AR1ZABYY		

*Materials that have been ordered are in **bold**.

Method of Identification: The firmware revision is printed on the product label

Micron Sites Affected: All Sites

Product Ship Date: 2019-07-09

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Attachments

There are no attachments on this PCN