



Micron 1300 Firmware Update M5MU010 and M5MA010

PCN: 33398

Published: 2019-08-19

Revision History:

RETRACTION: 2019-09-11. PCN 33398 is being retracted. Micron will delay the release of the 1300 FW Update. As a result, 1300 drives will continue shipping with M5MU000 and M5MA000.

Micron will provide an update on the new FW update availability via **PCN #33443** in October 2019.

This document supersedes the original PCN dated 2019-08-19.â€

Type:	Firmware Revision
Description:	<p>Changes and improvements made in firmware M5MU010/M5MA010 over previous firmware are:</p> <ul style="list-style-type: none">• Drive Activity Signal (DAS) was not reporting properly in some systems• General protocol and error handling improvements• Unexpected Power Loss improvements <p>Updating directly from all older revisions is supported. However, please note that reverting to any prior firmware revision is prevented after updating.</p>
Reason:	Improved Product Quality and Reliability

Product Affected: Micron 1300 SSD Family

Affected Micron Part Number Component	Recommended Replacement	Customer Part Number
MTFDDAK1T0TDL-1AW12ABYY		?
MTFDDAK1T0TDL-1AW1ZABYY		?
MTFDDAK256TDL-1AW12ABYY		?
MTFDDAK256TDL-1AW1ZABYY		?
MTFDDAK2T0TDL-1AW12ABYY		
MTFDDAK2T0TDL-1AW1ZABYY		
MTFDDAK512TDL-1AW12ABYY		
MTFDDAK512TDL-1AW1ZABYY		
MTFDDAV1T0TDL-1AW12ABYY		
MTFDDAV1T0TDL-1AW1ZABYY		
MTFDDAV256TDL-1AW12ABYY		?
MTFDDAV256TDL-1AW1ZABYY		?
MTFDDAV512TDL-1AW12ABYY		
MTFDDAV512TDL-1AW1ZABYY		

*Materials that have been ordered are in **bold**.

Method of Identification:	The firmware revision is printed on the label.
Micron Sites Affected:	All Sites
Product Ship Date:	2019-09-18

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments

There are no attachments on this PCN