



Micron 1300 Firmware Update M5MU030 and M5MA030

PCN: 33443

Published: 2019-10-07

Type: Firmware Revision

Description: Changes and improvements made in firmware M5MU030/M5MA030 over previous firmware are:

- Drive Activity Signal (DAS) was not reporting properly in some systems or during Slumber
- SMART ID 172 & 202 could report incorrect values
- General protocol and error handling improvements
- Unexpected Power Loss improvements

Updating directly from all older revisions is supported. However, please note that reverting to any prior firmware revision is prevented after updating.

**This PCN is the follow-on to PCN 33398 which was retracted on 2019-09-11.

Reason: Improved Product Quality and Reliability

Product Affected: Micron 1300 SSD Family

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>Solid State Storage</u>		
MTFDDAK1T0TDL-1AW12ABYY		?
MTFDDAK1T0TDL-1AW1ZABYY		?
MTFDDAK256TDL-1AW12ABYY		?
MTFDDAK256TDL-1AW1ZABYY		?
MTFDDAK2T0TDL-1AW12ABYY		
MTFDDAK2T0TDL-1AW1ZABYY		
MTFDDAK512TDL-1AW12ABYY		
MTFDDAK512TDL-1AW1ZABYY		
MTFDDAV1T0TDL-1AW12ABYY		
MTFDDAV1T0TDL-1AW1ZABYY		
MTFDDAV256TDL-1AW12ABYY		?
MTFDDAV256TDL-1AW1ZABYY		?
MTFDDAV512TDL-1AW12ABYY		
MTFDDAV512TDL-1AW1ZABYY		

*Materials that have been ordered are in **bold**.

Method of Identification: The firmware revision is printed on the label.

Micron Sites Affected: All Sites

Product Ship Date: 2019-11-06

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Attachments

There are no attachments on this PCN