



27-May-2019

PCN #:E-19-008351

Subject:SR6 6 pole Force Guided Relay

Description of Change: TE Connectivitys (TE) SR6 6 pole Force Guided Relay have a China Compulsory Certificate (CCC) mark of product certification. The Chinese Certification and Accreditation Authority (CNCA) has published new Implementation Rules for Compulsory Certification requiring reapproval by CCC. TE has been informed by CCC that as of May 8th, 2019 the certificate has been suspended. TE is expected to regain the CCC approval during the week of July 15 - 19, 2019. Until the product is recertified, TE will remove the CCC marking from the Force Guided Relay products SR6 effective with May 27, 2019. TE will notify our customers when we can apply the CCC mark to our Force Guided Relay products again which is expected in the week of July 15 - 19, 2019.

Reason: Document Clarification.

Key Dates:

Contact By Date:28-May-2019

Implementation Date:28-May-2019

Product Affected

6-1415027-1

(Alias Part Numbers:

"SR6D4024")

9-1415018-1

(Alias Part Numbers:

"V23050-A1110-A533"

"V23050A1110A533")

1415078-1

(Alias Part Numbers:

"SR6D4012")

Product Affected

4-1415543-2

(Alias Part Numbers:

"SR960017")

8-1415017-1

(Alias Part Numbers:

"V23050-A1005-A533"

"V23050A1005A533")

1393260-4

(Alias Part Numbers:

"V23050-A1012-A542"

"V23050A1012A542")

6-1415537-3

(Alias Part Numbers:

"SR6A6K18")

1-1415539-0

(Alias Part Numbers:

"SR960012")

7-1415537-9

(Alias Part Numbers:

"SR6B6K21")

1-1415544-5

3-1415353-1

(Alias Part Numbers:

"SR6M4024")

1393260-7

(Alias Part Numbers:

"V23050-A1024-A542"

"V23050A1024A542")

8-1415537-0

(Alias Part Numbers:

"SR6B6K24")

7-1415537-6

(Alias Part Numbers:

"SR6B6K12")

1-1393260-2

(Alias Part Numbers:

"V23050-A1085-A542"

"V23050A1085A542")

3-1415540-6

(Alias Part Numbers:

Product Affected

"SR960014")

7-1415541-9

(Alias Part Numbers:

"SR960016(SR6V6K18)")

3-1415018-1

(Alias Part Numbers:

"V23050-A1021-A533"

"V23050A1021A533")

1415539-9

(Alias Part Numbers:

"SR960011")

6-1415537-4

(Alias Part Numbers:

"SR6A6K21")

7-1415537-8

(Alias Part Numbers:

"SR6B6K18")

5-1415539-1

3-1415540-7

(Alias Part Numbers:

"SR900015")

8-1415537-1

(Alias Part Numbers:

"SR6B6K36")

6-1415018-1

(Alias Part Numbers:

"V23050-A1048-A533"

"V23050A1048A533")

3-1415543-3

(Alias Part Numbers:

"ANDERUNG"

"SR6V6K18")

4-1415545-3

1393260-6

(Alias Part Numbers:

"V23050-A1021-A542"

"V23050A1021A542")

1-1393260-3

(Alias Part Numbers:

"V23050-A1110-A542"

Product Affected

"V23050A1110A542")

7-1415537-2

(Alias Part Numbers:

"SR6B6K05")

7-1415018-1

(Alias Part Numbers:

"V23050-A1060-A533"

"V23050A1060A533")

9-1415537-0

(Alias Part Numbers:

"SR6C6K12")

4-1415545-2

6-1415537-1

(Alias Part Numbers:

"SR6A6K12")

5-1415019-1

(Alias Part Numbers:

"V23050-A1110-A551"

"V23050A1110A551")

1415015-1

(Alias Part Numbers:

"V23050-A1024-A533"

"V23050A1024A533")

3-1415532-1

(Alias Part Numbers:

"V23050A1018A542X07")

1415017-1

(Alias Part Numbers:

"V23050-A1024-A551"

"V23050A1024A551")

1-1415017-1

(Alias Part Numbers:

"V23050-A1012-A551"

"V23050A1012A551")

7-1415537-1

(Alias Part Numbers:

"SR6A6L10")

1-1393260-0

(Alias Part Numbers:

"V23050-A1048-A542"

Product Affected

"V23050A1048A542")

1-1415015-1

(Alias Part Numbers:

"V23050-A1012-A533"

"V23050A1012A533")

9-1415537-4

(Alias Part Numbers:

"SR6C6K24")

6-1415537-5

(Alias Part Numbers:

"SR6A6K24")

5-1415537-8

(Alias Part Numbers:

"SR6A6K05")

6-1415538-3

(Alias Part Numbers:

"SR960008")

1-1393260-1

(Alias Part Numbers:

"V23050-A1060-A542"

"V23050A1060A542")

1-1415539-1

(Alias Part Numbers:

"SR960010")

1393260-2

(Alias Part Numbers:

"V23050-A1006-A542"

"V23050A1006A542")

1393260-5

(Alias Part Numbers:

"V23050-A1018-A542"

"V23050A1018A542")

6-1415017-1

(Alias Part Numbers:

"V23050-A1018-A551"

"V23050A1018A551")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.