



09-Jul-2019

PCN #:E-19-010544

Subject:Materials Obsolescence, UOM change and Specification update for RBK-105-KIT Heat Shrink Tubing Products.

Description of Change: The following part numbers are being superseded (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application. Affected drawings will be managed on a separate PCN.

Reason: Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we have made the decision to supersede the parts stated thereafter. Due to an obsolescence of one of the raw materials used in the ATUM driver tubing (as previously notified in PCN P-18-015367) has enforced a modification to the tube material. IMDS records will be updated at the point of change over to the new material. The adhesive liner has not changed. We have also updated the specification for these kits as components used in assemblies for the original specification are no longer available. The new Specification reference is 108-120025. Please Note, In many cases the Unit of Measure has been changed so that now 1pc equals 1 termination. Previously 1pc equals 1 kit of 1000 terminations. Product is limited due to mat'l availability

Key Dates:

Last Order Date:05-Sep-2019

Last Ship/EOL Date:31-Dec-2019

Product Affected

CV0714-000

(Alias Part Numbers:

Recommended Replacement

EL6597-000

| Product Affected | Recommended Replacement |
|--|--------------------------------|
| "RBK-85-KIT-0105-B0" "4-1899812-5") | |
| 968711-000 (Alias Part Numbers: "6-1197489-0" "RBK-85-KIT-0203-A0") | EL6529-000 |
| 934817-000 (Alias Part Numbers: "4-1197243-9" "RBK-85-KIT-0504-A0") | EM9005-000 |
| 705721-001 (Alias Part Numbers: "4-1195534-5" "RBK-85-KIT-2110-A0") | EM9009-000 |
| 667797-000 (Alias Part Numbers: "3-1195259-1" "RBK-85-KIT-1308-A0") | EM9010-000 |
| 508471-000 (Alias Part Numbers: "4-1193997-8" "RBK-85-KIT-0405-A0") | EL6479-000 |
| 224707-000 (Alias Part Numbers: "2-1191655-8" "RBK-85-KIT-0107-A0") | EM9006-000 |
| 221285-000 (Alias Part Numbers: "6-1191630-4" "RBK-85-KIT-0102-A0") | EL6516-000 |
| 000691-000 (Alias Part Numbers: | EM8997-000 |

Product Affected

"3-1190005-2"

"RBK-85-KIT-0510-A0")

Recommended Replacement

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.