



05-Nov-2019

PCN #:E-19-015937

**Subject:**Superseding of SWFR X2 and X4, metric, unmarked, black parts

**Description of Change:** The following part numbers are being superseded (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application.

**Reason:** Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to supersed SWFR X2 and X4, metric, unmarked, black parts with SWFR X2 and X4, metric, marked, black parts.

**Key Dates:**

**Last Order Date:**07-Feb-2020

**Last Ship/EOL Date:**23-Mar-2020

Product Affected	Recommended Replacement
EJ1497-000	EM7496-000 (Alias Part Numbers:
EJ1508-000	EM7502-000 (Alias Part Numbers:
EJ1484-000	EM7486-000 (Alias Part Numbers:
EJ1492-000	EM7493-000 (Alias Part Numbers:
EJ1488-000	EM7489-000 (Alias Part Numbers:
EJ1514-000	EM7507-000

<b>Product Affected</b>	<b>Recommended Replacement</b>
EJ1486-000	(Alias Part Numbers: EM7488-000
EJ1502-000	(Alias Part Numbers: EM7497-000
(Alias Part Numbers: "X2-30.0-0-FSP")	(Alias Part Numbers: "X2-30.0-0-SP-SM")
EJ1489-000	EM7490-000
EJ1490-000	(Alias Part Numbers: EM7491-000
EJ1505-000	(Alias Part Numbers: EM7499-000
(Alias Part Numbers: "X4-0.8-0-SP")	(Alias Part Numbers: "X4-0.8-0-SP-SM")
EJ1482-000	EM7484-000
EJ1480-000	(Alias Part Numbers: EM7482-000
EJ1485-000	(Alias Part Numbers: EM7487-000
EJ2616-000	(Alias Part Numbers: EM7550-000
EJ2612-000	(Alias Part Numbers: EM7549-000
EJ1500-000	(Alias Part Numbers: EM7494-000
EJ1483-000	(Alias Part Numbers: EM7485-000
EJ1517-000	(Alias Part Numbers: EM7508-000
EJ1512-000	(Alias Part Numbers: EM7506-000
EJ1510-000	(Alias Part Numbers: EM7504-000
EJ1477-000	(Alias Part Numbers: EM7479-000
(Alias Part Numbers: "X2-1.0-0-SP"	(Alias Part Numbers: "X2-1.0-0-SP-SM"
"8-1899838-2")	)

**Product Affected**

EJ1506-000

(Alias Part Numbers:  
"X4-1.0-0-SP")

EJ1479-000

EJ2608-000

EJ1511-000

EJ1507-000

EJ1478-000

(Alias Part Numbers:  
"X2-1.5-0-SP"  
"8-1899838-6")

EJ1509-000

EJ1481-000

**Recommended Replacement**

EM7500-000

(Alias Part Numbers:  
"X4-1.0-0-SP-SM")

EM7481-000

(Alias Part Numbers:

EM7549-000

(Alias Part Numbers:

EM7505-000

(Alias Part Numbers:

EM7501-000

(Alias Part Numbers:

EM7480-000

(Alias Part Numbers:

"X2-1.5-0-SP-SM"

)

EM7503-000

(Alias Part Numbers:

EM7483-000

(Alias Part Numbers:

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.