



09-Apr-2019

PCN #:E-19-005729

Subject:Superseding of RNF-150 -SP parts migrating from Menlo Park, USA to Trutnov, CZ.

Description of Change: The following part numbers are being superseded (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application.

Reason: Discontinuance. Migration & Superseding. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. The affected part numbers have been identified as parts migrating from Menlo Park, USA to Trutnov, CZ for future manufacturing using new part numbers. The sales UOM for the replacement part numbers will change from FT to Metres for all -SP part numbers.

Key Dates:

Last Order Date:08-Jul-2019

Last Ship/EOL Date:31-Dec-2019

Product Affected

CR9826-000

7523674005

(Alias Part Numbers:

"1-1195866-1"

"RNF-150-3/32-0-SP")

6655094002

(Alias Part Numbers:

"5-1195243-9"

"RNF-150-1/2-9-SP")

Recommended Replacement

NB17234001

NB15774001

NB24574001

Product Affected	Recommended Replacement
5762674002 (Alias Part Numbers: "1-1194572-1" "RNF-150-1/8-0-SP")	NB15734001
530219M004 (Alias Part Numbers: "4-1194164-6" "RNF-150-1/4-0-SP")	NB15714001
5302194002 (Alias Part Numbers: "4-1194164-1" "RNF-150-1/4-0-SP")	NB15714001
5042414002 (Alias Part Numbers: "7-1193808-0" "RNF-150-3/16-9-SP")	NB15764001
5025074002 (Alias Part Numbers: "1193775-1" "RNF-150-3/8-0-SP")	NB15794001
4642074002 (Alias Part Numbers: "9-1193480-1" "RNF-150-1-0-SP")	NB17224001
2829894002 (Alias Part Numbers: "9-1192129-6" "RNF-150-1-9-SP")	NB17244001
2509914004 (Alias Part Numbers: "6-1191839-5" "RNF-150-3/16-0-SP")	NB15754001

Product Affected	Recommended Replacement
2283774002 (Alias Part Numbers: "3-1191680-6" "RNF-150-3/4-0-SP")	NB17254001
2029154002 (Alias Part Numbers: "1-1191471-8" "RNF-150-1/2-0-SP")	NB15704001
1918614002 (Alias Part Numbers: "6-1191391-1" "RNF-150-1/8-9-SP")	NB15744001
1637114002 (Alias Part Numbers: "4-1191181-6" "RNF-150-1/16-0-SP")	NB15694001
1615034002 (Alias Part Numbers: "1-1191166-7" "RNF-150-3/64-0-SP")	NB15784001
1518474002 (Alias Part Numbers: "7-1191097-6" "RNF-150-3/8-9-SP")	NB15804001
1121814002 (Alias Part Numbers: "7-1190818-7" "RNF-150-1/4-9-SP")	NB15724001

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.