



18-Jul-2019

PCN #:E-19-011155

Subject:SR6 / V23050 6 pole Force Guided Relay

Description of Change: As of July 15th 2019, TE Connectivitys SR6 6 pole Force Guided Relay has regained the approval to carry the China Compulsory Certificate (CCC) mark of product certification. Starting with Datecode 1930, all eligible SR6 Relays produced thereafter will have the CCC mark printed on them.

Reason: Document Clarification. The product has passed the new Implementation Rules for Compulsory Certification by the Chinese Certification and Accreditation Authority (CNCA), and is thus allowed to carry the CCC mark again.

Key Dates:

Contact By Date:19-Jul-2019

Implementation Date:19-Jul-2019

Product Affected

6-1415027-1

(Alias Part Numbers:

"SR6D4024")

9-1415018-1

(Alias Part Numbers:

"V23050-A1110-A533"

"V23050A1110A533")

1415078-1

(Alias Part Numbers:

"SR6D4012")

4-1415543-2

(Alias Part Numbers:

"SR960017")

Product Affected

8-1415017-1

(Alias Part Numbers:

"V23050-A1005-A533"

"V23050A1005A533")

1393260-4

(Alias Part Numbers:

"V23050-A1012-A542"

"V23050A1012A542")

6-1415537-3

(Alias Part Numbers:

"SR6A6K18")

9-1415538-1

(Alias Part Numbers:

"SR960009")

1-1415539-0

(Alias Part Numbers:

"SR960012")

7-1415537-9

(Alias Part Numbers:

"SR6B6K21")

1-1415544-5

3-1415353-1

(Alias Part Numbers:

"SR6M4024")

1393260-7

(Alias Part Numbers:

"V23050-A1024-A542"

"V23050A1024A542")

8-1415537-0

(Alias Part Numbers:

"SR6B6K24")

7-1415537-6

(Alias Part Numbers:

"SR6B6K12")

1-1393260-2

(Alias Part Numbers:

"V23050-A1085-A542"

"V23050A1085A542")

3-1415540-6

(Alias Part Numbers:

Product Affected

"SR960014")

7-1415541-9

(Alias Part Numbers:

"SR960016(SR6V6K18)")

3-1415018-1

(Alias Part Numbers:

"V23050-A1021-A533"

"V23050A1021A533")

1415539-9

(Alias Part Numbers:

"SR960011")

6-1415537-4

(Alias Part Numbers:

"SR6A6K21")

7-1415537-8

(Alias Part Numbers:

"SR6B6K18")

5-1415539-1

3-1415540-7

(Alias Part Numbers:

"SR900015")

8-1415537-1

(Alias Part Numbers:

"SR6B6K36")

6-1415018-1

(Alias Part Numbers:

"V23050-A1048-A533"

"V23050A1048A533")

3-1415543-3

(Alias Part Numbers:

"ANDERUNG"

"SR6V6K18")

4-1415545-3

1393260-6

(Alias Part Numbers:

"V23050-A1021-A542"

"V23050A1021A542")

1-1393260-3

(Alias Part Numbers:

"V23050-A1110-A542"

Product Affected

"V23050A1110A542")

7-1415537-2

(Alias Part Numbers:

"SR6B6K05")

7-1415018-1

(Alias Part Numbers:

"V23050-A1060-A533"

"V23050A1060A533")

9-1415537-0

(Alias Part Numbers:

"SR6C6K12")

4-1415545-2

6-1415537-1

(Alias Part Numbers:

"SR6A6K12")

5-1415019-1

(Alias Part Numbers:

"V23050-A1110-A551"

"V23050A1110A551")

1415015-1

(Alias Part Numbers:

"V23050-A1024-A533"

"V23050A1024A533")

3-1415532-1

(Alias Part Numbers:

"V23050A1018A542X07")

1415017-1

(Alias Part Numbers:

"V23050-A1024-A551"

"V23050A1024A551")

1-1415017-1

(Alias Part Numbers:

"V23050-A1012-A551"

"V23050A1012A551")

7-1415537-1

(Alias Part Numbers:

"SR6A6L10")

1-1393260-0

(Alias Part Numbers:

"V23050-A1048-A542"

Product Affected

"V23050A1048A542")

1-1415015-1

(Alias Part Numbers:

"V23050-A1012-A533"

"V23050A1012A533")

9-1415537-4

(Alias Part Numbers:

"SR6C6K24")

6-1415537-5

(Alias Part Numbers:

"SR6A6K24")

5-1415537-8

(Alias Part Numbers:

"SR6A6K05")

6-1415538-3

(Alias Part Numbers:

"SR960008")

1-1393260-1

(Alias Part Numbers:

"V23050-A1060-A542"

"V23050A1060A542")

1-1415539-1

(Alias Part Numbers:

"SR960010")

1393260-2

(Alias Part Numbers:

"V23050-A1006-A542"

"V23050A1006A542")

1393260-5

(Alias Part Numbers:

"V23050-A1018-A542"

"V23050A1018A542")

6-1415017-1

(Alias Part Numbers:

"V23050-A1018-A551"

"V23050A1018A551")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.